

Affected Model

- Emperor & Albatross

Reported Issue

- Speedo intermittently failing and/or showing inaccurate readings

Initial Action

The most common reason for the abovementioned issue to occur is something quite simple to diagnose & rectify

Please check the Speed Sensor Gap, it should be 3mm (not 7mm as pictured below). Make the relevant adjustment to this gap and this will rectify the issue

