

Dealer Service Bulletin # DB111

TG900RS – Not Charging

REPORTED FAULT : Scooter not charging when plugged into charger correctly

INDICATIONS OF FAULT: Fan on the charger not operating
Charging light remains RED

POSSIBLE ISSUE: Loose connections at either the Circuit Board or Controller

ACTION TO BE TAKEN: Check the charging line on the circuit board, which is located on the inside of the rear tiller cover, is firmly connected and not loose.

Follow the charging line to the controller which is located near the drive motor and check this connection is also firm.

