

Dealer Service Bulletin # DSB116

TRANZFORMA – Disconnected Plug Issue

When this problem occurs the scooter will give 3 short beeps and then 2 short beeps

Please see the plug being pointed to. Check this plug as the factory advises this particular plug in the bank of plugs may have come out and is not connecting with the other end of the plug.

