

Dealer Service Bulletin # DSB133

Mustang Hi/Low Failure

ISSUE:

No difference in hi/low function. Scooter will only travel at full speed. No change in speed when adjusting the speed level (tortoise-rabbit buttons).

SCOOTER AFFECTED :

Mustang

REQUIRED ACTION:

Check whether below two pins are loose: the purple one refers to H/L function and the green one means tortoise-rabbit adjusting. Generally this issue results in one or both of these pins being loose.

