

Dealer Service Bulletin # DSB138

Error Code 42 – Flytemax 2

If error code 42 comes up on your Flytemax 2 or is a recurring code, this is the process to stop it happening. Make sure this process is conducted with a little force so as not to damage the connector. If you are unsure or have any concerns. Please call Top Gun Mobility

