

Applicable Model:

- Mustang
- Everest
- Daytona
- Safari
- Charger
- Blazer

Settings:

The screenshot shows a settings window titled "Inhibit Settings" with the following configuration:

Setting	Value
Inhibit 1: Mode	1
Inhibit 1: Operation	<input type="radio"/> Non-Latching <input checked="" type="radio"/> Latching
Inhibit 1: Speed (%)	0
Inhibit 2: Mode	1
Inhibit 2: Operation	<input checked="" type="radio"/> Non-Latching <input type="radio"/> Latching
Inhibit 2 Speed (%)	80

A red arrow points from the "Inhibit 2: Mode" setting to the "1" value.

Mustang should be set at 50%

Safari should be set at 50%

Everest should be set at 85%

Charger should be set at 80%

Daytona should be set at 80%

Blazer should be set at 60%